## The Mighty Civic

Civic Theatre Refurbishment Architectural Aspects

**Hunter Gillies** 













Figure 4 Site preparation for the new Civic Theatre showing the use of steam showels and turnes to excusure for foundations, 1929, Auckland building and Museum, Neg C22744













GITE





## CONCEPT SECTION

